



572/40	A=19	C=12	D=Ø6	E=10	L=40	S=1,5
572/60	A=29	C=12	D=Ø6	E=10	L=60	S=1,5
572/80	A=39	C=16	D=Ø7	E=13	L=80	S=2
572/100	A=48	C=16	D=Ø7	E=13	L=98	S=2
572/120	A=58	C=20	D=Ø9	E=16	L=119	S=3
572/140	A=68	C=20	D=Ø9	E=16	L=139	S=3

