



| |  | A | B | C | D | E | F |
|-----------------------|---|-----|-----|-----|----|----|----|
| GBMU-X-M16-110 | 200 kg | M16 | 110 | 85 | 40 | 30 | 42 |
| GBMU-X-M18-105 | 250 kg | M18 | 105 | 80 | 50 | 30 | 42 |
| GBMU-X-M20-130 | 400 kg | M20 | 130 | 105 | 60 | 35 | 51 |
| GBMU-X-M22-145 | 440 kg | M22 | 145 | 115 | 60 | 35 | 51 |

| |  | G | H | I | J | K | L |
|-----------------------|---|-----|----|----|----|----|------|
| GBMU-X-M16-110 | 200 kg | 110 | 45 | 17 | 8 | 60 | |
| GBMU-X-M18-105 | 250 kg | 120 | 50 | 19 | 8 | 62 | |
| GBMU-X-M20-130 | 400 kg | 130 | 60 | 21 | 12 | | 86,5 |
| GBMU-X-M22-145 | 440 kg | 130 | 60 | 23 | 12 | 74 | |